

Torque Tester

ZV011

 7.7  1 / 1

Calibration Range	2~60 N·m
Accuracy	± 0.5%
Units of Measurement	in·lb, ft·lb, Kgf·m, Kgf·cm, N·m, N·cm
Input Hex A/F (mm)	10mm
Square Drive Adaptor (inch)	1/4", 3/8", 1/2"
Operating Temperature Range	+5°C~ +40°C
Storage Temperature Range	+0°C~ +70°C
Power Input	100-240V DC9.0V±1.66A, 15W MAX
Base Material / Finish	Aluminum Alloy / Painting
Dimension	210(L) x 150(W) x 140(H) mm




ZV011A		Europe
ZV011B		America & Asia
ZV011D		Australia & New Zealand

ZV012

 8.1  1 / 1

Calibration Range	8~400 N·m
Accuracy	± 0.5%
Units of Measurement	in·lb, ft·lb, Kgf·m, Kgf·cm, N·m, N·cm
Input Hex A/F (mm)	22mm
Square Drive Adaptor (inch)	3/8", 1/2", 3/4"
Operating Temperature Range	+5°C~ +40°C
Storage Temperature Range	+0°C~ +70°C
Power Input	100-240V DC9.0V±1.66A, 15W MAX
Base Material / Finish	Aluminum Alloy / Painting
Dimension	210(L) x 150(W) x 140(H) mm



ZV012A		Europe
ZV012B		America & Asia
ZV012D		Australia & New Zealand

ZV013

 8.9  1 / 1

Calibration Range	100~1500 N·m
Accuracy	± 0.5%
Units of Measurement	in·lb, ft·lb, Kgf·m, Kgf·cm, N·m
Input Hex A/F (mm)	36mm
Square Drive Adaptor (inch)	3/4"
Operating Temperature Range	+5°C~ +40°C
Storage Temperature Range	+0°C~ +70°C
Power Input	100-240V DC9.0V±1.66A, 15W MAX
Base Material / Finish	Aluminum Alloy / Painting
Dimension	210(L) x 150(W) x 140(H) mm



ZV013A		Europe
ZV013B		America & Asia
ZV013D		Australia & New Zealand